



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
July 16, 2007

Supervisor DRZ

Mine Name: Heber Red Quarry
Operator Name: Paul Fitzgerald Contractors

Permit number: S/051/003
Inspection Date: July 16, 2007
Time: 12:30 pm

Inspector(s): Lynn Kunzler, DOGM
Other Participants: None
Mine Status: Inactive

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls,
8. Soils
9. Revegetation

Evaluated	Comment	Enforcement
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection while in the area.

Inspection Summary:

This site was inactive. It appeared that there has been no activity for some time (grass was growing between the grouser tracks on the trackhoe). Only 28 ton of rock was reported quarried since 2002. Other than a couple of small (ca. 10-20 cu yds) piles, it appeared as if most of the area had been regarded and possibly seeded (highwalls were sloped to between 2h:1v and 3h:1v slope. Vegetation has established over the area (currently about 50% ground cover – surrounding vegetation was estimated at 70% cover). Species observed included aster, horehound, oak, rabbitbrush, sagebrush, crested wheatgrass, western wheatgrass, slender wheatgrass, fescue, bluegrass, smooth brome, squireltail, and sweetclover. Cheatgrass was also present but not considered in estimating the % ground cover.

Photos were taken to document site conditions.

Conclusions and Recommendations:

This site appears to meet reclamation success standard. File could be closed if operator so desires.

Inspector's Signature LK

LK:pb

O:\M051-Wasatch\S0510003-HeberRed\inspections\Insp-07162007.doc